


Labor and Materials

1	Copper	Connection	3	\$ 1.33
1	Curb	Cock		
		Valve	3	\$ 1.58
		T.S.C.V.	4	
1	Service Box	Short 3 1/2 x 4 1/2		\$ 1.36
	Old returned	Long 4 1/2 x 5 1/2		
		Both or B.Way		
13	Ft. in.	Copper	3	\$ 1.17
		Galv. Iron	4	
		Cast Iron		
		Pipe at		
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g Inc'g	Couplings to in. at		\$
	Union	in. at		\$
	Meter	in. at		\$
	Lbs. Br. Stone	at		\$
	Lbs. Sand	at		\$
	Bags Cement	at		\$
	Paving Brick	Mack		\$
		Red		\$
		Asphalt		\$
	Lead Joints	at		\$
	Leadite Joints	at		\$
5	Hrs. Foreman	at	3.13	\$
4	Hrs. Common Labor	at Tappan	2.00	\$
11	Hrs. Common Labor	at	4.95	\$
	Hrs. Mason	at		\$
	Hrs. Masons Helper	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins		31	\$
	Trucking		1	\$
	Builders Use of Water	Patch	5	\$
Total \$				21.83

83-1

Labor and Material Report *Dec* 3 1932

16 *Marion Ave*



4 Main Elev. of Main at tap 5

Gate at ● Gate at ●

● Curb Box

TAX ID # 302.20-4-15

Shut off at Main

O.R. G.H.