

Labor and Materials

Copper	Connection	\$ 3.20
Lead		
Curb	Cock Valve T.S. & V. in.	\$ 1.00
Service Box	Short 3 1/2 x 4 1/2	\$ 1.30
Old returned	Long 4 1/2 x 5 1/2 Buff. or Rdway	
1/8 Ft. 5/8 in.	Copper Galv. Iron Cast Iron Pipe at.	\$ 39.6
Nipples	in. at.	\$
Bushings	to in. at.	\$.08
Red'g Inc's	Couplings to in. at.	\$ 15
Union	in. at.	\$
Meter	in. at.	\$
Lbs. Br. Stone	at.	\$
Lbs. Sand	at.	\$
Bags Cement	at.	\$
Paving Brick	Mack Red Asphalt at.	\$
Lead Joints	at.	\$
Leadite Joints	at.	\$
1 Hrs. Foreman	at. 62.5	\$ 63
9 Hrs. Common Labor	at. 50	\$ 450
15 Hrs. Common Labor	at. 40.7	\$ 609
Hrs. Mason	at.	\$
Hrs. Mason's Helper	at.	\$
Hrs. Compressor	at.	\$
Compensation Ins.		\$ 30
Trucking		\$ 1.00
Builders' Use of Water		\$
Total		\$ 2221.

Labor and Material Report

1926

Sept 11
no 19 mainline app.



4" Main Elev. of Main at tap 5'
Gate at ● Gate at ●

● Curb Box

TAX ID # 302.20-7-13