

Labor and Materials

1	Copper	Connection	\$	1.48
1	Lead	Cock	\$	1.79
1	Curb	Valve in	\$	1.79
1	Service Box	Long 4 1/2 x 5 1/2	\$	1.46
17	Ft.	Copper in	\$	3.06
		Cast Iron in. at	\$	
		Nipples in. at	\$	
		Bushings to in. at	\$	
		Red'g to in. at	\$	
		Inc'g to in. at	\$	
		Union in. at	\$	
		Meter in. at	\$	
		Lbs. Br. Stone	at	\$	
		Lbs. Sand	at	\$	
		Bags Cement	at	\$	
		Paving Brick at	\$	
		Lead Joints	at	\$	
		Leadite Joints	at	\$	
2	Hrs.	Foreman	at	\$	1.25
4	Hrs.	Common Labor	at	\$	2.00
9	Hrs.	Common Labor	at	\$	4.05
	Hrs.	Mason	at	\$	
	Hrs.	Masons Helper	at	\$	
	Hrs.	Compressor	at	\$	
		Compensation Ins	\$	2.23
		Trucking	\$	
		Builders Use of Water	Patch	\$	5.00
				Total \$	21.32

5 32-139
 Labor and Material Report Nov 23 1932
 15 Marcell Ave

6 Main Elev. of Main at tap 44
 Gate at ● Curb Box ● Gate at

● Curb Box

old Tap to be found.

TAX ID # 302.20-7-11

o/k [Signature]