

Labor and Materials

1	Copper } Connection	3	\$ 320
	Lead } "	3	
1	Curb { Cock } in.	3	\$ 100
	{ Valve } "		
	{ T.S. & V. } "		
1	Service Box { Short 3 1/2 x 4 1/2 }		\$ 130
	Old returned { Long 4 x 5 1/2 }		
	{ Buff or Railway }		
1	6 Ft. in. { Copper } Pipe at	3	\$ 418
	{ Galv. Iron } "		
	{ Cast Iron } "		
	Nipples in. at		\$
	Bushings to in. at		\$
	Red'g } Couplings to in. at		\$
	Inc'g } "		
	Union in. at		\$
	Meter in. at		\$
	Lbs. Br. Stone at		\$
	Lbs. Sand at		\$
	Bags Cement at		\$
	Paving Brick { Mack } at		\$
	{ Red } "		
	{ Asphalt } "		
	Lead Joints at		\$
	Leadite Joints at		\$
3	Hrs. Foreman at		\$ 187
	Hrs. Common Labor at		\$
16	Hrs. Common Labor at		\$ 650
	Hrs. Mason at		\$
	Hrs. Mason's Helper at		\$
	Hrs. Compressor at		\$
	Compensation Ins.		\$ 22
1	Trucking		\$ 100
	Builders' Use of Water		\$
Total			\$ 1927

27-124 6 1927
 Labor and Material Report Aug 3 1927

2 Mason at

31'7" 22'8" 31'7"

Curb Box

Main Elev. of Main at tap 5

Gate at Gate at

Curb Box

New House