

Labor and Materials

1	Copper } Connection $\frac{3}{4}$ "	\$ 3.20
1	Curb } Cock Valve } $\frac{3}{4}$ " in.	\$ 1.00
		T.S. & V.
1	Service Box } Short 3' x 4' }	\$ 1.30
	Old returned } Long 4' x 5' }	
		Buff. or Rdway
19	Ft. $\frac{3}{4}$ " in. } Copper } Pipe at.	\$ 4.18
		Galv. Iron
		Cast Iron
	Nipples..... in. at.....	\$
	Bushings..... to..... in. at.....	\$
	Red'g } Couplings..... to..... in. at.....	\$
	Inc'g }	
	Union..... in. at.....	\$
	Meter..... in. at.....	\$
	Lbs. Br. Stone at.....	\$
	Lbs. Sand at.....	\$
	Bags Cement at.....	\$
	Paving Brick } Mack } at.....	\$
		Red }
		Asphalt }
	Lead Joints at.....	\$
	Leadite Joints at.....	\$
5	Hrs. Foreman at..... $6\frac{1}{2}$	\$ 63
3	Hrs. Common Labor at..... $6\frac{1}{2}$	\$ 188
3	Hrs. Common Labor at..... 50	\$ 150
2	Hrs. Mason " "..... $4\frac{1}{8}$	\$ 127
	Hrs. Mason's Helper at.....	\$
	Hrs. Compressor at.....	\$
	Compensation Ins.....	\$ 1.4
	Trucking.....	\$ 120
	Builders' Use of Water.....	\$
	Total \$ <u>16.05</u>	

28

Labor and Material Report *april 13* 19*18*

no. 4 main st.

28

11" Main Elev. of Main at tap 5"

Gate at ● ● Gate at

● Curb Box

new y or
new face

Tax ID # 302.12.16.20