

LABOR AND MATERIALS

1	Copper Lead	Connection	3/4"	\$ 1.23
1	Curb	Cock Valve F. S. & V.	3/4" in.	\$ 1.68
1	Service Box Old returned	Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff. or Rdway		\$ 1.54
10 Ft.	3/4 in.	Copper Galv Iron Cast Iron	Pipe at	\$ 3.06
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g Inc'g	Couplings	to in. at	\$
	Union	in. at		\$
	Meter	in. at		\$
	Lead Joints	at		\$
	Leadite Joints	at		\$
	Hrs. Foreman	at		\$
5	Hrs. Chauffeur	at	.62 1/2	\$ 3.13
8	Hrs. Tapper	at	"	\$ 5.00
8	Hrs. Labor	at	.45	\$ 3.60
	Hrs. Labor	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins.			\$.36
	Trucking			\$ 1.00
	Builders Use of Water	Patch		\$ 5.00
		Taps, Hoses & Pipes		\$
				\$
				\$
				\$
				\$
				\$ 35.60

21 - 1939

St. 36
Pl.
Ave. No. 32

Mason

Name of Owner

Dark

Labor and Mat'l. Report May 18

1939



4" Main

Elev. of
Main at tap 5'

Gate at ●

● Gate at

● Curb Box

Old tap disconnected.
Tax ID# 302.12-16-24

DM