

### LABOR AND MATERIALS

1	Copper	{ Connection	3/4	\$	2.29
1	Lead			\$	
1	Curb	{ Cock Valve	3/4" in.	\$	2.70
		{ T.S. & V.			
1	Service box	{ Short	3 1/2 x 4 1/2	\$	4.25
	Old returned	{ Long	4 1/2 x 5 1/2		
		{ Buff or Rdway			
11	Ft.	{ Copper		\$	3.85
	3/4 in.	{ G.I.	Pipe at 35		
		{ C.I.			
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g	{ Coupl'gs	to in. at	\$	
	Inc'g				
	Union	in. at		\$	
	Meter	in. at		\$	
	Lead Joints	at		\$	
	Compound Joints	at		\$	
	Hrs. Water Maint. Man-1	at		\$	
3	Hrs. Water Maint. Man-2	at	107	\$	306.15
8	Hrs. Labor	at	91	\$	729.15
	Hrs. Labor	at		\$	
	Hrs. Compressor	at		\$	
	Compensation Ins. at \$2.26	per C.		\$	23
	Trucking			\$	1.00
	Pav't Patch	Ext. Main		\$	
	Tap by Moquin			\$	
	O'head			\$	
				\$	24.66

1950

-Str  
Pl.  
Ave. No. 2

Name of Owner Mauro Pozzuoli

Labor and Mat'l. Report Oct 3 1950

Elev. of Main at tap 5'

Gate at ● ● Gate at

● Curb Box

Tax map # 303.9-7-31

LSM-5C 10-21-49