

LABOR AND MATERIALS

1 Copper { Connection $\frac{3}{4}$ } ----- \$

1 Curb { Cock } ----- in. \$

1 Service Box { ~~W.S. & V.~~ } ----- \$

Old returned { Short $3\frac{1}{2} \times 4\frac{1}{2}$ } } ? \$

 { Long $4\frac{1}{2} \times 5\frac{1}{2}$ } } \$

 { Buff. or Rdway } } \$

25 $\frac{3}{4}$ in. { Copper } Pipe at ----- \$

 { Galv. Iron } } \$

 { Cast Iron } } \$

Nipples ----- in. at ----- \$

Bushings ----- to ----- in. at ----- \$

Red'g } Couplings ----- to ----- in. at ----- \$

Inc'g } } \$

Union ----- in. at ----- \$

Meter ----- in. at ----- \$

Lead Joints at ----- \$

Leadite Joints at ----- \$

Hrs. Foreman at ----- \$

Hrs. Chauffeur at ----- \$

Hrs. Tapper at ----- \$

Hrs. Labor at ----- \$

Hrs. Labor at ----- \$

Hrs. Compressor at ----- \$

Compensation Ins. ----- \$

Trucking ----- \$

Builders Use of Water ----- \$

----- \$

----- \$

----- \$

----- \$

----- \$

----- \$

----- \$

St. **27**
Pl.
Ave. No. **17**

May

Name of Owner

Labor and Mat'l. Report

1912



● Curb Box

8" 1976

Main

Elev. of
Main at tap

Gate at ●

● Gate at

● Curb Box

Tax Map # 302.20-18.4