

Labor and Materials

Copper } Connection	3/4	\$ 2.60
Curb } Cock Valve	3/4	\$ 2.30
Service Box } Short 3/4x1/2		\$ 1.40
Old returned } Long 1/2x3/8		
	Bull or Rdway	
7'-6" 3/4 in. } Copper	3	\$ 2.39
	Galv. Iron	
	Cast Iron	
Nipples	in. at	\$
Bushings	to in. at	\$
Red'g } Couplings	to in. at	\$
Inc'g }		
Union	in. at	\$
Meter	in. at	\$
Lbs. Br. Stone	at	\$
Lbs. Sand	at	\$
Bags Cement	at	\$
Paving Brick } Mack		\$
	Red	
	Asphalt	
Lead Joints	at	\$
Leadite Joints	at	\$
3 Hrs. Foreman	at	\$ 1.88
1.4 Hrs. Common Labor	at	\$ 5.69
Hrs. Common Labor	at	\$
Hrs. Mason	at	\$
Hrs. Mason's Helper	at	\$
Hrs. Compressor	at	\$
Compensation Ins.		\$ 15
Trucking		\$ 1.00
Builders' Use of Water	Patch	\$ 5.00
Total		22.41

29-197 4
Labor and Material Report Nov 12 1924

2 May 21



18" 1976
 Main

Elev of Main at tap

Gate at ● Gate at ●

● Curb Box

May tap disconnected

Tax Map # 302.20-9-25