

Labor and Materials

1	Copper } Connection	3/4"	\$3.20
1	Curb } Cock Valve } T.S. & V.	3/4" in.	\$1.00
1	Service Box } Old returned	Short 3/4 x 4 } Long 4 1/2 x 5 } Buff. or Rdway	\$1.40
3'-6"	Ft. } 3/4" in. } Copper Galv. Iron } Cast Iron	Pipe at.	\$1.54
	Nipples	in. at.	\$
	Bushings	to in. at.	\$
	Red'g } Inc'g } Couplings	to in. at.	\$
	Union	in. at.	\$
	Meter	in. at.	\$
	Lbs Br. Stone	at.	\$
	Lbs. Sand	at.	\$
	Bags Cement	at.	\$
	Paving Brick } Mack Red Asphalt	at.	\$
	Lead Joints	at.	\$
	Leadite Joints	at.	\$
5	Hrs. Foreman	62.5	\$3.12
	Hrs. Common Labor		\$
20	Hrs. Common Labor	4.12	\$8.12
	Hrs. Mason		\$
	Hrs. Mason's Helper		\$
	Hrs. Compressor		\$
	Compensation Ins.		\$30
	Trucking		\$1.00
	Builders' Use of Water		\$
Total			\$19.68

27-76 6 June 9 1927
 Labor and Material Report

3/4 May 27

8"-1976
 Main Elev. of Main at tap 5'
 Gate at ● Gate at ●
 ● Curb Box

New tap
 2 Hacer on same
 1 tap
 Tax Map # 302.20-9-26