

LABOR AND MATERIALS

1	Copper Lead	{ Connection $\frac{3}{4}$ "	\$
1	Curb	{ Cock Valve } $\frac{3}{4}$ " in.	\$
1	Service Box Old returned	{ Short $3\frac{1}{2} \times 4\frac{1}{2}$ Long $4\frac{1}{2} \times 5\frac{1}{2}$ Buff. or Rdway } ?	\$
23	Ft. $\frac{3}{4}$ in.	{ Copper Galv Iron Cast Iron } Pipe at	\$
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g Inc'g	{ Couplings to in. at	\$
	Union	in. at	\$
	Meter	in. at	\$
	Lead Joints	at	\$
	Leadite Joints	at	\$
	Hrs. Foreman	at	\$
	Hrs. Chauffeur	at	\$
	Hrs. Tapper	at	\$
	Hrs. Labor	at	\$
	Hrs. Labor	at	\$
	Hrs. Compressor	at	\$
	Compensation Ins.		\$
	Trucking		\$
	Builders Use of Water		\$
			\$
			\$
			\$
			\$
			\$
			\$

197-26

St. 7
~~Pl.~~
 Ave. No. 3

May

Name of Owner
White

Labor and Mat'l. Report Sept 22 1936

15' 7" 19' 4"

● Curb Box

8" - 1976

Main Elev. of Main at tap 5'

Gate at ● ● Gate at

● Curb Box

Remeasured 6-24-75