

Labor and Materials

Copper } Connection.....	\$ 2.70
Lead }	
Curb } Cock Value }	\$ 2.39
} T. S. & V. }	
Service Box } Short 3/4x4 1/2 }	\$ 1.45
Old returned } Long 4 1/2x5 1/2 }	
} Buff. or Rdway }	
Ft. in. } Copper } Pipe at 3 }	\$ 1.89
} Galv. Iron }	
} Cast Iron }	
Nipples..... in. at.....	\$
Bushings..... to..... in. at.....	\$
Red'g } Couplings..... to..... in. at.....	\$
Inc'g }	
Union..... in. at.....	\$
Meter..... in. at.....	\$
Lbs. Br. Stone at.....	\$
Lbs. Sand at.....	\$
Bags Cement at.....	\$
Paving Brick } Mack } at.....	\$
} Red }	
} Asphalt }	
Lead Joints at.....	\$
Leadite Joints at.....	\$
2 Hrs. Foreman at.....	\$ 1.25
1.2 Hrs. Common Labor at.....	\$ 5.40
Hrs. Common Labor at.....	\$
Hrs. Mason at.....	\$
Hrs. Mason's Helper at.....	\$
Hrs. Compressor at.....	\$
Compensation Ins.....	\$.21
Trucking.....	\$ 1.-
Builders' Use of Water.....	\$ 5.-
Total \$ 21.29	

30-26

19

Labor and Material Report

Aug

19

15 Madison St



8"-1975

Main Elev of Main at tap 53

Gate at ● ● Gate at

● Curb Box

old gas disconnected