

### Labor and Materials

1	Board Connection	3	\$
1	Curb Cock	3	\$
1	Service Box	(Short 4 1/2 x 6)	\$
	Old returned	(Long 4 1/2 x 6)	\$
40	Ft. in G. I. Pipe at	Copper	\$
	Nipples	in. at	\$
	Bushings	to in. at	\$
1	Red'g Coup	3/4 to in. at	\$
	Inc'g Coup	to in. at	\$
	Union	in. at	\$
	Meter	in. at	\$
	Cu. Yds. Br. Stone at		\$
	Cu. Yds. Sand at		\$
	Bags Cement at		\$
	Paving Brick	{ Mack Red Asphalt } at	\$
	Hrs. Foreman at		\$
30	Hrs. Common Labor at		\$
	Hrs. Mason at		\$
4	Hrs. Penor		\$
	Hrs.		\$
	Builders' Use of Water		\$
	Truck		\$ 1.00
			\$
			\$
	Total		\$ 28.57

20 July 3 1924  
Labor and Material Report

1691 Donald St.



8"-1925

Gate at ● Main Elev. of Main at tap 5

TAX ID # 303.18-11-14.3

● Curb Box