

Labor and Materials

Copper } Connection.....	3	\$ 2.70
Lead }	4	\$ 2.39
Curb { Cock }		
{ Valve }		
{ T.S. & V. }		
Service Box } Short 3/4x4 1/2 }		
Old returned } Long 4 1/2x5 1/2 }		\$ 1.45
{ Buff or Rdway }		
Ft. in. } Copper } Pipe at.....	3	\$ 2.16
{ Galv. Iron }		
{ Cast Iron }		
Nipples..... in. at.....		\$
Bushings..... to..... in. at.....		\$
Red'g } Couplings..... to..... in. at.....		\$
Inc'g }		\$
Union..... in. at.....		\$
Meter..... in. at.....		\$
Lbs. Br. Stone at.....		\$
Lbs. Sand at.....		\$
Bags Cement 'at.....		\$
Paving Brick { Mack } at.....		\$
{ Red }		\$
{ Asphalt }		\$
Lead Joints at.....		\$
Leadite Joints at.....		\$
4 Hrs. Foreman at.....		\$ 2.50
13 Hrs. Common Labor at.....		\$ 5.85
Hrs. Common Labor at.....		\$
Hrs. Mason at.....		\$
Hrs. Mason's Helper at.....		\$
Hrs. Compressor at.....		\$
Compensation Ins.....		\$ 26
Trucking.....		\$ 1 -
Builders' Use of Water Patch.....		\$ 5 -
Total \$		23.31

30-87
 Labor and Material Report 19 30



8" 1975
 Main Elev of Main at tap
 Gate at Gate at

● Curb Box

Old tap disconnected

21 TAX ID # 303.18-12-8