

**Labor and Materials**

1	Copper	Connection		\$ 3.20
	Lead			
1	Curb	Cock Valve	2 1/2 in.	\$ 1.00
		P.S. & V.		
1	Service Box	Short 3 1/2 x 4 1/2		\$ 1.30
	Old returned	Long 4 1/2 x 5 1/2		
		Buff. or Rdway		
33	Ft.	3/4 in. Copper Galv. Iron Cast Iron	Pipe at	\$ 7.26
	Nipples	in. at		\$
	Bushings	to in. at		\$
1	Red g. Ink	Couplings	2 1/2 to 3 in. at	\$ 1.50
	Union	in. at		\$
	Meter	in. at		\$
	Lbs. Br. Stone	at		\$
	Lbs. Sand	at		\$
	Bags Cement	at		\$
	Paving Brick	Mack Red Asphalt	at	\$
	Lead Joints	at		\$
	Leadite Joints	at		\$
7	Hrs. Foreman	at	6 2/3	\$ 4.38
2	Hrs. Common Labor	at	6 2/3	\$ 1.25
7	Hrs. Common Labor	at	50	\$ 3.50
	Hrs. Mason	at		\$
	Hrs. Mason's Helper	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins.			\$ 24
	Trucking			\$ 1.00
	Builders' Use of Water			\$
Total				\$ 23.28

28-13 26-30

Labor and Material Report Apr 9 1928

3/4" tap at 22 M<sup>o</sup> Donald at

22 M<sup>o</sup> Donald at

26-30

14' 9" 8' 0" Curb Box

8"-1975

Main Eley. of Main at tap 6 ft

Gate at ● Gate at ●

● Curb Box

Water turned on

#26 - #32 TAX ID # 303.18-5-2