

Labor and Materials

1	Copper } Connection	3/4	\$	320
	Lead }		\$	
1	Curb } Cock Valve } T.S. & V. }	3/4 in.	\$	100
1	Service Box } Short 3 1/2 x 4 1/2 } Old returned } Long 4 1/2 x 5 1/2 } Bull. or Rdway }		\$	130
27	Ft. } 3/4 in. } Copper } Galv. Iron } Cast Iron }		\$	594
	Nipples.....	in. at.....	\$	
	Bushings.....	to..... in. at.....	\$	
1	Red'g } Couplings. } 3/4 to..... in. at.....		\$	1.17
	Union.....	in. at.....	\$	
	Meter.....	in. at.....	\$	
	Lbs. Br. Stone at.....		\$	
	Lbs. Sand at.....		\$	
	Bags Cement at.....		\$	
	Paving Brick } Mack } Red } Asphalt }	at.....	\$	
	Lead Joints at.....		\$	
	Leadite Joints at.....		\$	
4	Hrs. Foreman at.....	6.25	\$	250
12	Hrs. Common Labor at.....	50	\$	600
12	Hrs. Common Labor at.....	40 1/2	\$	488
	Hrs. Mason at.....		\$	
	Hrs. Mason's Helper at.....		\$	
	Hrs. Compressor at.....		\$	
	Compensation Ins.....		\$	25
1.45	Trucking.....		\$	150
4.95	Builders' Use of Water.....		\$	
Total			\$	2632

Labor and Material Report

Apr 15

1927

no 54 one Donald St



8.1925

X Main

Elev. of Main at tap 5'

Gate at ●

● Gate at

● Curb Box

new tap
new house