

Labor and Materials

Copper } Connection.....	3	\$ 3.20
Lead } Cock	4	
Curb } Valve		\$ 1.00
T.S. & V.		
Service Box } Short 3 1/2 x 4 1/2		\$ 1.20
Old returned } Long 4 1/2 x 5 1/2		
Butt or Rdway }		
6 Ft. } in. } Copper	3	\$ 1.76
in. } Galv. Iron	4	
Cast Iron		
Nipples.....	in. at.....	\$
Bushings.....	to..... in. at.....	\$
Red'g } Couplings.....	to..... in. at.....	\$
Inc'g }		
Union.....	in. at.....	\$
Meter.....	in. at.....	\$
Lbs. Br. Stone at.....		\$
Lbs. Sand at.....		\$
Bags Cement at.....		\$
Paving Brick } Mack		\$
Red		
Asphalt }	at.....	\$
Lead Joints at.....		\$
Leadite Joints at.....		\$
7 Hrs. Foreman at.....		\$ 2.10
1 1/2 Hrs. Common Labor at.....		\$ 6.00
1 1/4 Hrs. Common Labor at.....		\$ 4.75
Hrs. Mason at.....		\$
Hrs. Mason's Helper at.....		\$
Hrs. Compressor at.....		\$
Compensation Ins.....		\$ 3.8
Trucking.....		\$ 1.00
Builders' Use of Water.....		\$
Total		\$ 27.83

28-132

63

Labor and Material Report

Oct 2, 1925

45 M Donald St



8-1975

Main

Elev. of Main at tap

3 1/2

Gate at

TAX ID # 303.14-2-27

Gate at

Curb Box

Old Tap Shut off
REVERSE