

LABOR AND MATERIALS

1	Copper Lead } Connection	3/4	\$	1.59
1	Curb } Cock Valve T-S. & V.	3/4 in.	\$	2.74
1	Service Box Old returned	{ Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff for Rdway }	\$	1.82
36	Ft. 3/4 in.	{ Copper Galv Iron Cast Iron }	Pipe at 19	\$ 6.84
	Nipples	in. at	\$	
	Bushings	to in. at	\$	
	Red'g Inc'g } Couplings	to in. at	\$	
	Union	in. at	\$	
	Meter	in. at	\$	
	Lead Joints at		\$	
	Leadite Joints at		\$	
	Hrs. Foreman at		\$	
32	Hrs. Chauffeur at	6.8 3/4	\$	22.00
	Hrs. Tapper at		\$	
90	Hrs. Labor at	6.2 1/2	\$	12.50
	Hrs. Labor at		\$	
8	Hrs. Compressor at	8.7 1/2	\$	7.00
	Compensation Ins.		\$	92
	Trucking		\$	1.00
	Builders Use of Water		\$	5.00
	<i>Topsy Miller</i>			
	<i>old taps dug up & shut off</i>			
			\$	
			\$	
			\$	
			\$	
			\$	
			\$	
			\$	61.41

4-45

St. 64
Pt. 46
Ave. No. 46

McDonald

Name of Owner
Sullivan

Labor and Mat'l. Report Apr 5 1945

23'11" 17'7"
● Curb Box

8" 1975 Main Elev. of Main at tap 4 1/2

● Gate at ● Gate at

TAX ID # 303.17-7-3

● Curb Box