

Labor and Materials

1	Copper	Connection	3/4	\$ 1.48
1	Lead			
1	Curb	Cock Valve g.S.&V.	in	\$ 1.79
1	Service Box	Short 3 1/2 x 4 1/2		\$ 1.30
	Old returned	Long 4 1/2 x 5 1/2		
		Buff. or Rdway		
7	Ft.	Copper Galv. Iron Cast Iron	Pipe at 3/4	\$ 1.26
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g Inc'g	Couplings to in. at		\$
	Union	in. at		\$
	Meter	in. at		\$
	Lbs. Br. Stone	at		\$
	Lbs. Sand	at		\$
	Bags Cement	at		\$
	Paving Brick	Mack Red Asphalt	at	\$
	Lead Joints	at		\$
	Leadite Joints	at		\$
4	Hrs. Foreman	at		\$ 2.50
4	Hrs. Common Labor	at Tapper		\$ 2.00
8	Hrs. Common Labor	at		\$ 3.60
	Hrs. Mason	at		\$
	Hrs. Masons Helper	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins			\$ 2.5
	Trucking			\$ 1.00
	Builders Use of Water	Patch		\$ 5.00
Total				\$ 20.18

532-1110 65

Labor and Material Report Sept 22 1932

47 McDonald St

8" 1945

Main Elev. of Main at tap 52

Gate at ● Gate at ●

● Curb Box

old Tap & shut off at Main,

TAX ID # 303.14-2-26

OK [Signature]