

**Labor and Materials**

1	Copper	Connection	3	\$ 3.20
1	Curb	Cock Valve	1	\$ 1.00
1	Service Box	Short 3/4x4 1/2		\$ 1.30
10	Pt.	Copper	3	\$ 2.20
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g Inc'g	Couplings to in. at		\$
	Union	in. at		\$
	Meter	in. at		\$
	Lbs. Br. Stone	at		\$
	Lbs. Sand	at		\$
	Bags Cement	at		\$
	Paving Brick	Mack Red Asphalt at		\$
	Lead Joints	at		\$
	Leadite Joints	at		\$
3	Hrs. Foreman	at		\$ 1.58
11	Hrs. Common Labor	at		\$ 4.47
	Hrs. Common Labor	at		\$
	Hrs. Mason	at		\$
	Hrs. Mason's Helper	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins			\$ 17
	Trucking			\$ 1.00
	Builders' Use of Water			\$
Total \$				15.22

28-172 67 A-B  
 Labor and Material Report Sept 19 1928  
 49-Mc Donald at  
 67 A-B  
 20-6  
 20-6  
 Curb Box  
 8" 1975  
 Main Elev of Main at tap 4 1/2  
 Gate at Curb Box  
 Old shut off  
 TAX ID # 303.14-2-25