

Labor and Materials

1	Copper } Connection	3/4	\$ 320
1	Lead } Cock	3/4	
1	Curb } Valve	3/4	\$ 100
		T.S. & V.	
	Service Box	Short 3 1/2 x 4 1/2	\$ 140
	Old returned	Long 4 1/2 x 5 1/2	
		Buff. or Rdway	
8	Ft. 3/4 in. } Copper		\$ 198
		Galv. Iron	
		Cast Iron	
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g } Couplings	to in. at	\$
	Inc'g		
	Union	in. at	\$
	Meter	in. at	\$
	Lbs. Br. Stone	at	\$
	Lbs. Sand	at	\$
	Bags Cement	at	\$
	Paving Brick	{ Mack } at	\$
		{ Red }	
		{ Asphalt }	
	Lead Joints	at	\$
	Leadite Joints	at	\$
2	Hrs. Foreman	62 1/2	\$ 125
6	Hrs. Common Labor	50	\$ 300
9	Hrs. Common Labor	48	\$ 366
	Hrs. Mason	at	\$
	Hrs. Mason's Helper	at	\$
	Hrs. Compressor	at	\$ 21
	Compensation Ins.		\$ 1.50
1	Trucking		\$
	Builders' Use of Water		\$
	Total		\$ 1670

86 ~~87-86-86A~~

Labor and Material Report *May 12* 19 *26*

7.4 *McDonald*

8" 1975

Main Elev. of Main at tap *5*

Gate at Gate at

● Curb Box

TAX ID # 303.13-22-5

New taps