

Labor and Materials

1	Copper	Lead	Connection	3/4"	\$	1.33
1	Curb	Cock Valve T.S.&V.	3/4" in		\$	1.58
1	Service Box	Old returned	Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Ball or Rawls		\$	1.36
10	Ft.	3/4" in	Copper Galv. Iron Cast Iron	Pipe at	\$	9.5
	Nipples			in. at	\$	
	Bushings			to in. at	\$	
	Red'g Inc'g	Couplings		to in. at	\$	
	Union			in. at	\$	
	Meter			in. at	\$	
	Lbs. Br. Stone			at	\$	
	Lbs. Sand			at	\$	
	Bags Cement			at	\$	
	Paving Brick	Mack Red Asphalt		at	\$	
	Lead Joints			at	\$	
	Leadite Joints			at	\$	
5	Hrs. Foreman			at	\$	5.00
5	Hrs. Common Labor			at	\$	2.50
	Hrs. Common Labor			at	\$	
	Hrs. Mason			at	\$	
	Hrs. Masons Helper			at	\$	
	Hrs. Compressor			at	\$	
	Compensation Ins				\$.23
	Trucking				\$	1.00
	Builders Use of Water	Patch			\$	5.00
					Total	\$18.95

33-22

Labor and Material Report May 11

1933

3/4" tap at 79 McDonald St



8"-1975

X" Main

Elev. of Main at tap 4.11

Gate at TAX ID # 303.14-2-15

Gate at

Old tap shut off

OK-924

M