

Labor and Materials

1	Copper	Connection	3	\$ 3.20
1	Lead			
1	Curb	Cock Valve T. B. & V.	3/4 in.	\$ 1.00
1	Service Box	Short 3/4 x 3/4		\$ 1.40
1	Old returned	Long 3/4 x 5/8		
9	Pt.	Copper Galv. Iron Cast Iron	3/4 in. Pipe at	\$ 15.40
	Nipples		in. at	\$
	Bushings		to in. at	\$
1	Red's	Couplings	3/4 to 3/4 in. at Cop. to Cop.	\$
	Union		in. at	\$
	Meter		in. at	\$
	Lbs. Br. Stone	at		\$
	Lbs. Sand	at		\$
	Bags Cement	at		\$
	Paving Brick	Mack Red Asphalt	at	\$
	Lead Joints	at		\$
	Leadite Joints	at		\$
2	Hrs. Foreman	at		\$ 18.80
1	Hrs. Common Labor	at		\$ 5.00
8	Hrs. Common Labor	at		\$ 32.50
	Hrs. Mason	at		\$
	Hrs. Mason's Helper	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins			\$ 14
	Trucking			\$ 100
	Builders' Use of Water			\$
Total \$				13.93

78-124 15- left 21

Labor and Material Report 1928

11 Mc Donald St.

8" - 1958

Main Elev of Main at tap 5'

Gate at ● Gate at ●

● Curb Box

all top shut off

TAX ID # 303.18-12-11