

Labor and Materials

1	Copper } Connection	3/4	\$3.20
1	Lead } Curb		
		Cock	
		in.	\$1.00
		T.S. & V.	
1	Service Box	Short 3 1/2 x 4 1/2	
	Old returned	Long 4 1/2 x 5 1/2	\$1.20
		Buff. or Rdway	
19	Ft. 3/4 in.	Copper	
		Galv. Iron	
		Cast Iron	
		Pipe at	\$4.18
1	Nipples	3/4 in. at	\$1.00
	Bushings	to in. at	\$
1	Reduc'g } Couplings	3/4" to 1" in. at	\$1.50
	Union	in. at	\$
	Meter	in. at	\$
	Lbs Br. Stone	at	\$
	Lbs. Sand	at	\$
	Bags Cement	at	\$
	Paving Brick	{ Mack } at	\$
		{ Red }	
		{ Asphalt }	
	Lead Joints	at	\$
	Leadite Joints	at	\$
8	Hrs. Foreman	at 6.25	\$5.00
14	Hrs. Common Labor	at 50	\$7.00
15	Hrs. Common Labor	at 40 5/8	\$6.09
	Hrs. Mason	at	\$
	Hrs. Mason's Helper	at	\$
	Hrs. Compressor	at	\$
	Compensation Ins.		\$49
	Trucking		\$1.00
	Builders' Use of Water		\$
500 for digging up old top.			
Total			\$29.51

FEB 8 1927

31
Labor and Material Report Aug 30 1926

13 Mohican St



4" Main Elev. of Main at tap 5
Gate at ● Gate at ●

● Curb Box

Leonard Morrison
CURB STOP ON - ON OFF
POSITION
Tax ID# 309.36-28
(Hospital)