

Labor and Materials

1 Copper } Connection		\$ 320
Lead } Connection		
1 Curb } Cock		\$ 100
Valve } in.		
T.S. & V. }		
1 Service Box } Short 3 1/2 x 4 1/2		\$ 140
Old returned } Long 4 1/2 x 5 1/2		
Buff. or Rdway }		
10 Ft. 3/4 in. } Copper		\$ 220
Galv. Iron } Pipe at		
Cast Iron }		
Nipples..... in. at.....		\$
Bushings..... to..... in. at.....		\$
Red'g } Couplings..... to..... in. at.....		\$
Inc'g }		
Union..... in. at.....		\$
Meter..... in. at.....		\$
Lbs. Br. Stone at.....		\$
Lbs. Sand at.....		\$
Bags Cement at.....		\$
Paving Brick } Mack		\$
Red }		
Asphalt }		
Lead Joints at.....		\$
Leadite Joints at.....		\$
8 Hrs. Foreman at..... 6.25		\$ 500
Hrs. Common Labor at.....		\$
85 Hrs. Common Labor at..... 4.08		\$ 345
Hrs. Mason at.....		\$
Hrs. Mason's Helper at.....		\$
Hrs. Compressor at.....		\$
Compensation Ins.....		\$ 125
Trucking.....		\$ 100
Builders' Use of Water.....		\$
Total		\$ 978

Labor and Material Report 1926

Vacant lot Fitzgerald & Canal St
 11' 0"
 43' 11"
 3' 7"
 Curb Box Vacant lot

4" Main Elev. of Main at tap 10'
 Gate at Gate at

Curb Box
 Abandoned to original
 intended for gas station
 N.W. cor. of Blk. Blackland?
 ?

Vacant lot Fitzgerald & Canal St