

Labor and Materials

| | |
|---|-------|
| Lead Connection | \$ |
| Curb Cock | \$ |
| Service Box (Short 3½ x 4½ Old returned (Long 4½ x 5½ Buffalo | \$ |
| 20 Ft. . . . in. G. I. Pipe at | \$ |
| Nipples | \$ |
| Bushings | \$ |
| Red'g Coup | \$ |
| Inc'g Coup | \$ |
| Union | \$ |
| Meter | \$ |
| Cu. Yds. Br. Stone at | \$ |
| Cu. Yds. Sand at | \$ |
| Bags Cement at | \$ |
| Paving Brick { Mack Red } at | \$ |
| Hrs. Foreman at | \$ |
| Hrs. Common Labor at | \$ |
| Hrs. Mason at | \$ |
| Hrs. at | \$ |
| Hrs. at | \$ |
| Builders' Use of Water | \$ |
| <i>Int. Tank Charge</i> | \$ |
| at | \$ |
| at | \$ |
| at | \$ |
| Total \$ | 10.38 |

52 Oct. 30 19

Labor and Material Report

30 Mohicans St.

19' 3" 19" 24" Curb Box

4 Main Elev. of Main at tap 4

Gate at ● Gate at ●

● Curb Box

Tax ID# 309.36-3-6