

Labor and Materials

1	Copper	Connection	1	\$ 1.48	
1	Curb	Cock Valve T.S.&V.	1	\$ 1.79	
					in
1	Service Box	Old returned	1	\$ 1.30	
					Short 3/4 x 4 1/4 Long 4 1/4 x 5 1/4 Buff. or Redway
22	Ft.	in.	3	\$ 3.96	
					Copper Galv. Iron Cast Iron
	Nipples	in. at	1	\$	
	Bushings	to in. at		\$	
	Red'g Inc'g	Couplings	to in. at	\$	
	Union	in. at		\$	
	Meter	in. at		\$	
	Lbs. Br. Stone	at		\$	
	Lbs. Sand	at		\$	
	Bags Cement	at		\$	
	Paving Brick	at		\$	
					Mack
					Red Asphalt
	Lead Joints	at		\$	
	Leadite Joints	at		\$	
5	Hrs. Foreman	at	3	\$ 13.	
19	Hrs. Common Labor	at	8	\$ 55.	
	Hrs. Common Labor	at		\$	
	Hrs. Mason	at		\$	
	Hrs. Masons Helper	at		\$	
	Hrs. Compressor	at		\$	
	Compensation Ins			\$ 36.	
	Trucking			\$ 1.00	
	Builders Use of Water	Patch		\$ 5.00	
Total				\$ 76.59	

632-37 54 Labor and Material Report May 7 1932

32 Indian St



4 Main Elev. of Main at tap 5 1/2'

Gate at ● Gate at ●

● Curb Box  
old tap sent off

Tax ID # 309.36-3-7

D.D.