

Labor and Materials

1. Copper } Connection $3/4$	\$.96
1. Lead } Connection $3/4$	\$.96
1. Curb { Cock } $3/4$ in	\$ 1.33
1. Curb { Valve } $3/4$ in	\$ 1.33
1. Curb { T.S.&V. } $3/4$ in	\$ 1.33
1. Service Box { Short $3\frac{1}{2} \times 4\frac{1}{2}$ } Old returned { Long $4\frac{1}{2} \times 5\frac{1}{2}$ } Buff. or Rdway.	\$ 1.35
22 Ft. $3/4$ in. { Copper } Galv. Iron } Pipe at 15	\$ 3.30
Cast Iron }	
Nipples in. at	\$
Bushings to in. at	\$
Red'g } Couplings to in. at	\$
Inc'g }	
Union in. at	\$
Meter in. at	\$
Lbs. Br. Stone at	\$
Lbs. Sand at	\$
Bags Cement at	\$
Paving Brick { Mack } Red } at	\$
Asphalt }	
Lead Joints at	\$
Leadite Joints at	\$
5 Hrs. ^{Chief} Foreman at $62\frac{1}{2}$	\$ 3.13
16 Hrs. Common Labor at 45	\$ 7.20
Hrs. Common Labor at	\$
Hrs. Mason at	\$
Hrs. Masons Helper at	\$
Hrs. Compressor at	\$
Compensation Ins	\$ 32
Trucking	\$ 1
Builders Use of Water ^{Patch}	\$ 5
Total \$	23.59

Labor and Material Report

Sept 2

1954



4" Main

Elev. of Main at tap 4

Gate at • Tax ID #309.36-3-18 Gate at

● Curb Box

Old tap about off

[Handwritten signature]

Remove old Buffalo Box

Sept. 22, 1954

Removed Sept 23, 1954