LABOR AND MATERIALS

1	Copper ~~Lead~~ Connection	3/4	$ 1.23
1	Curb { Cock ~~Valve~~ ~~T. S. &~~ V. }	3/4 in.	$ 1.68
1	Service Box Old returned { Short 3½x4½ Long 4½x5½ Buff. or Rdway }		$ 1.54
21	Ft. ____ in. { Copper ~~Galv Iron~~ ~~Cast Iron~~ } Pipe at 17		$ 3.57
____	Nipples ____ in. at		$
____	Bushings ____ to ____ in. at		$
____	Red'g Inc'g Couplings ____ to ____ in. at		$
____	Union ____ in. at		$
____	Meter ____ in. at		$
____	Lead Joints at		$
____	Leadite Joints at		$
____	Hrs. Foreman at		$
8	Hrs. Chauffeur at	62½	$ 5.00
____	Hrs. Tapper at		$
8	Hrs. Labor at	45	$ 3.60
____	Hrs. Labor at		$
____	Hrs. Compressor at		$
____	Compensation Ins.		$ 26
____	Trucking		$ 1.—
____	Builders Use of Water	Patch	$ 5.00
			$
			$
			$
			$
			$ 22.88

7 4 -- 1939

St. 72
~~Pl.~~
Mohigan Ave. No. 46

Name of Owner

Cooney

Labor and Mat'l. Report Sept 16 1939

TAX ID# 309.36-3-14

4 Main

Elev. of Main at tap 5'

Gate at ● ● Gate at

21' to main

● Curb Box

Old tap shut off