

Labor and Materials

1	Copper	Connection	3/4	\$	3.70
	Lead				
1	Curb	Cock Valve T.S. & V.	3/4 in.	\$	1.00
1	Service Box	Short 3/2x4 1/2		\$	1.30
	Old returned	Long 4 1/2x5 1/2			
		Buff. or Rdway			
2	Ft.	Copper Galv. Iron Pipe at	2 1/2 in.	\$	46.2
		Cast Iron			
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g	Couplings	to in. at	\$	
	Inc'g				
	Union	in. at		\$	
	Meter	in. at		\$	
	Lbs. Br. Stone	at		\$	
	Lbs. Sand	at		\$	
	Bags Cement	at		\$	
	Paving Brick	Mack Red Asphalt at		\$	
	Lead Joints	at		\$	
	Leadite Joints	at		\$	
3	Hrs. Foreman	at		\$	18.8
4	Hrs. Common Labor	at		\$	18.3
	Hrs. Common Labor	at		\$	
	Hrs. Mason	at		\$	
	Hrs. Mason's Helper	at		\$	
	Hrs. Compressor	at		\$	
	Compensation Ins.			\$.09
	Trucking			\$	1.00
	Builders' Use of Water			\$	
				Total \$	147.2

Labor and Material Report

28-15976 Oct 25 1928

50 Mohican St



4' Main
 Gate at ● 21' to MAIN ● Gate at
 Elev of Main at tap 5'

● Curb Box