

### Labor and Materials

Copper } Connection.....	3/4	\$
Lead } .....		\$
Curb { Cock } .....	3/4	\$
{ Valve } .....		\$
{ T. S. & V. } .....		\$
Service Box { Short 3 1/2 x 4 1/2 } .....		\$
Old returned { Long 4 1/2 x 5 1/2 } .....		\$
{ Buff. or Rdway } .....		\$
1/4 Ft. 2 1/2 in. { Copper } Pipe at.....		\$
{ Galv. Iron } .....		\$
{ Cast Iron } .....		\$
Nipples..... in. at.....		\$
Bushings..... to..... in. at.....		\$
Red'g } Couplings..... to..... in. at.....		\$
Inc'g } .....		\$
Union..... in. at.....		\$
Meter..... in. at.....		\$
Lbs. Br. Stone at.....		\$
Lbs. Sand at.....		\$
Bags Cement at.....		\$
Paving Brick { Mack } at.....		\$
{ Red } .....		\$
{ Asphalt } .....		\$
Lead Joints at.....		\$
Leadite Joints at.....		\$
Hrs. Foreman at.....		\$
Hrs. Common Labor at.....		\$
Hrs. Common Labor at.....		\$
Hrs. Mason at.....		\$
Hrs. Mason's Helper at.....		\$
Hrs. Compressor at.....		\$
Compensation Ins.....		\$
Trucking.....		\$
Builders' Use of Water.....		\$
<b>Total \$.....</b>		

Labor and Material Report

19 26

Mohican St Vacant lot (front)

See other side

West side

● Curb Box

4 Main

Elev. of Main at tap

Gate at ●

● Gate at

● Curb Box