

Labor and Materials

..... Lead Connection	\$	
..... 1 Curb Cock ^{5/8}	\$	1.32
..... 1 Service Box (Short 3' x 4')	\$	1.55
..... 1 Old returned (Long 4' x 5')	\$	
..... 24 Ft. ^{3/4} in. G. I. Pipe at	\$	2.88
..... 1 Nipples ^{1/2} in. at	\$.12
..... Bushings..... in. at	\$	
..... Red'g Coup... to... in. at	\$	
..... Inc'g Coup... to... in. at	\$	
..... Union... in. at	\$	
..... Meter... in. at	\$	
..... Cu. Yds. Br. Stone at	\$	
..... Cu. Yds. Sand at	\$	
..... Bags Cement at	\$	
..... Pav. Brick { Mack { Red { Asphalt } at	\$	
..... 4 Hrs. Foreman at	\$	1.75
..... 4 Hrs. Com. Labor at	\$	1.25
..... Hrs. Mason at	\$	
..... Hrs. at	\$	
..... Hrs. at	\$	
..... Builders' Use of Water	\$	
..... at	\$	
..... at	\$	
..... at	\$	
..... at	\$	
Total	\$	8.87

13
Labor and Material Report

Nov 20 1919

1/2" Rensselaer at 8 Jefferson



6" Main

Elev. of Main at tap 5'-1"

Gate at ●

● Gate at

● Curb Box

was 2.