

**Labor and Materials**

1	Copper	} Connection.. 3/4 in	\$ 1.75
1	Lead		
1	Curb	} Cock Valve T.S.&V. } 3/4 in	\$ 1.70
1	Service Box		
	Old returned	{ Short 3 1/2 x 4 1/2 } { Long 4 1/2 x 5 1/2 } { Buff. or Rdway }	\$ 1.37
24	Ft. 3/4 in	{ Copper Galv. Iron } { Cast Iron }	Pipe at 13 1/2 \$ 3.24
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g Inc'g	} Couplings.....to.....in.at	\$
	Union	in. at	\$
	Meter	in. at	\$
	Lbs. Br. Stone	at	\$
	Lbs. Sand	at	\$
	Bags Cement	at	\$
	Paving Brick	{ Mack Red Asphalt }	at \$
	Lead Joints		at \$
	Leadite Joints	at \$	
5 1/2	Hrs. Foreman	at 6 1/2	\$ 3.44
3 1/2	Hrs. Common Labor	at 50	\$ 6.75
2 1/2	Hrs. Common Labor	at 45	\$ 9.45
	Hrs. Mason	at	\$
	Hrs. Masons Helper	at	\$
	Hrs. Compressor	at	\$
	Compensation Ins		\$ 57
	Trucking		\$ 1-
	Builders Use of Water		\$
Total			\$ 73.77

1935-118

Labor and Material Report *Aug 19* 19*35*

*3/4" tap at 12 Mantel cabinet.*

10" Main Elev. of Main at tap 5

Gate at ● ● Gate at

● Curb Box

*This <sup>old</sup> tap to be dug up.*

*Dug up and shut off main to be paid for*

*116*

TAX ID # 309.27-6-29