

Labor and Materials

| | | | | |
|----|-----------------------|----------------|---------------|----|
| 1 | Copper | Connection | 3/4" | \$ |
| 1 | Curb | Cock | 3/4" Oriseal | \$ |
| 1 | Service Box | Short | 3 1/2 x 4 1/2 | \$ |
| | Old returned | Long | 4 1/2 x 5 1/2 | \$ |
| | | Buff. or Rdway | | \$ |
| 12 | Ft. 3/4 in. | Copper | | \$ |
| | | Cast Iron | Pipe at | \$ |
| | Nipples | in. at | | \$ |
| | Bushings | to in. at | | \$ |
| | Red'g | Conplings | to in. at | \$ |
| | Inc'g | | | \$ |
| | Union | in. at | | \$ |
| | Meter | in. at | | \$ |
| | Lead Joints | at | | \$ |
| | Leadite Joints | at | | \$ |
| | Hrs. Foreman | at | | \$ |
| | Hrs. Chauffeur | at | | \$ |
| | Hrs. Tapper | at | | \$ |
| | Hrs. Labor | at | | \$ |
| | Hrs. Labor | at | | \$ |
| | Hrs. Compressor | at | | \$ |
| | Compensation Ins. | | | \$ |
| | Trucking | | | \$ |
| | Builders Use of Water | | | \$ |
| | Tap by | DAMOKAM T. CO. | | \$ |
| | | 8-25-70, | | \$ |
| | | | | \$ |
| | | | | \$ |
| | | | | \$ |

St. Morton
 Pl. 20
 Ave. No. 20

Name of Owner
Mrs. James Arthur,

Labor and Mat'l. Report Aug. 25 1970

22' 8" 29' 8" Curb Box

6" Tap on Morton St.
 Main Elev. of 6'
 Main at tap

Gate at ● ● Gate at

● Curb Box

Tax ID # 309.7-8-24