

### Labor and Materials

1	Copper	Connection	3/4"	\$ 2.41
1	Lead			
1	Curb	Cock Valve	3/4 in	\$ 3.41
1	Service Box	Short 3 1/2 x 4 1/2	}	\$ 4.18
	Old returned			
28	3/4 in.	Copper	Pipe at 40	\$ 11.20
		Galv Iron		
		Cast Iron		
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g	Conplings	to in. at	\$
	Inc'g			
	Union	in. at		\$
	Meter	in. at		\$
	Lead Joints	at		\$
	Leadite Joints	at		\$
	Hrs. Foreman	at		\$ 20.56
	Hrs. Chauffeur	at		\$
2	Hrs. Tapper	at M.M. 2 - 1.24		\$ 2.48
16	Hrs. Labor	at 1.13		\$ 18.08
	Hrs. Labor	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins.	286.1		\$ 29
	Trucking			\$ 150
	Builders Use of Water			\$ 16.20
	Top made 12-7-53			\$
	By Gifford			\$
				\$
				\$
				\$
				\$ 60.75

44.05

1-4  
 St. 640  
 Pl. Munsick  
 Ave. No. 2

Name of Owner Rose

Labor and Mat'l. Report 12-7 1953



4" Main Elev. of Main at tap 5'

Gate at 28' to main Gate at

Curb Box

TAX ID# 302.12-21-2