

Labor and Materials

1	Copper	Connection	3/4"	\$	308
1	Lead			\$	
1	Curb	Cock Valve	3/4" in	\$	389
		T. S. & V.		\$	
1	Service Box	Short	3 1/2 x 4 1/2	\$	432
	Old returned	Long	4 1/2 x 5 1/2	\$	
		Buff. or Rdway		\$	
11	Ft.	Copper	3/4" in.	\$	45
		Galv Iron		\$	495
		Cast Iron		\$	
	Nipples	in. at		\$	
	Bushings	in. to in. at		\$	
	Red'g	Conplings	to in. at	\$	
	Inc'g			\$	
	Union	in. at		\$	
	Meter	in. at		\$	
	Lead Joints	at		\$	
	Leadite Joints	at		\$	
	Hrs. Foreman	at		\$	
	Hrs. Chauffeur	at		\$	
	Hrs. Tapper	at		\$	
	Hrs. Labor	at		\$	
	Hrs. Labor	at		\$	
	Hrs. Compressor	at		\$	
	Compensation Ins.	5686		\$	
	Trucking			\$	1.50
	Builders Use of Water	Below Paving		\$	
	Tap by	Gibson & Co.		\$	
		6-29-56		\$	

Nelson

St. ✓

11

Pt.

Aver. No. 7

Name of Owner

G.F. Grange Hall.

Labor and Mat'l. Report

JUNE 29 1956



6"

Main

Elev. of

Main at tap

Gate at ●

● Gate at

● Curb Box

Renewal before

Paving.

TAX ID# 302.20-11-19

Date of old Tap 11-10-22 ¹⁹