Labor and Materials

1	Connection	$
1	Curb Cock	$
1	Service Box (Short 3½ x 4½ / Long 4½ x 5½ / Buffalo) Old returned	$
23	Ft. in. G. I. Pipe at	$
	Nipples in. at	$
	Bushings to in. at	$
1	Red'g Coup to in. at	$
	Inc'g Coup to in. at	$
	Union in. at	$
	Meter in. at	$
	Cu. Yds. Br. Stone at	$
	Cu. Yds. Sand at	$
	Bags Cement at	$
	Paving Brick (Mack / Red / Asphalt) at	$
7	Hrs. Foreman at	$
14	Hrs. Common Labor at	$
	Hrs. Mason at	$
	Hrs. at	$
	Hrs. at	$
9 M	Builders' Use of Water	$
	at	$
Truck 100	at	$
	at	$
	at	$
	Total	$ 20.75

Labor and Material Report June 6 1924

¾ Tap at 9+11 Mc Brayer

9+11 New Curb

29' 3"

24' 10"

22'

24' 10"

Curb Box

Old corp Shut off

8" Main

Elev. of Main at tap

Gate at

Gate at

Curb Box

Tax ID# 309.28-5-7