

Labor and Materials

1	Copper } Connection	\$
	Lead }	
1	Curb { Cock Valve } 3/4 in.	\$
	{ P.S. & V. }	
2	Service Box { Short 3 1/2 x 4 1/2 } Old returned { Long 4 1/2 x 5 1/2 } { Buff. or Rdway }	\$
12	Pt. in. { Copper Galv. Iron } Pipe at	\$
	Nipples in. at	\$
	Bushings 1/2 to 3/4 in. at	\$
	Red'g } Couplings to in. at	\$
	Inc'g }	
	Union in. at	\$
	Meter in. at	\$
	Lbs. Br. Stone at	\$
	Lbs. Sand at	\$
	Bags Cement at	\$
	Paving Brick { Mack Red Asphalt } at	\$
	Lead Joints at	\$
	Leadite Joints at	\$
2	Hrs. Foreman at	\$
11	Hrs. Common Labor at	\$
	Hrs. Common Labor at	\$
	Hrs. Mason at	\$
	Hrs. Mason's Helper at	\$
	Hrs. Compressor at	\$
	Compensation Ins.	\$
	Trucking	\$
	Builders' Use of Water	\$
	Total \$	

27-212

Labor and Material Report

19

#14 Sprung NEW



Curb Box

10 Main

Elev. of Main at top

Gate at ●

● Gate at

● Curb Box

old Top Slut off

Tax ID# 309.28-9-4