

No Corp Stop

**LABOR AND MATERIALS** .53

1	Copper	3/4" Male Adapter Connection Same	\$	
	Lead			
1	Curb	Cock Valve T. S. & V.	in.	\$ 3.54
1	Service box Old returned	Short 3/4x4 1/2 Long 4 1/2x5 1/2 Buff or Rdway		\$ 4.70
9	Ft. 3/4" in.	Copper G.I. G.I.	Pipe at .35	\$ 3.15
	Nipples	in. at		\$
1	Bushings	3/4" to 1/2" in. at		\$ 15
	Red'g Ine'g	Coupl'gs to in. at		\$
	Union	in. at		\$
	Meter	in. at		\$
	Lead Joints	at		\$
	Compound Joints	at		\$
	Hrs. Water Maint. Man-1	at		\$
8	Hrs. Water Maint. Man-2	at 1.13		\$ 9.04
1	Hrs. Labor	at 1.26		\$ 1.26
12	Hrs. Labor	at 1.02		\$ 12.24
	Hrs. Compressor	at		\$
	Compensation Ins. at \$	per C.		\$ 60
	Trucking			\$ 1.00
	Pav't Patch			\$ 6.75
	O'head			\$
				\$ 42.96

Tap by Carlford  
Jan 51

26-1951

St.  
Pt.  
North Delaware Ave. No. 5

Name of Owner Guay

Labor and Mat'l. Report JUNE 1 1951

No 5

● Curb Box

2" Galv Main      Elev. of Main at tap 6'

Gate at ●      ● Gate at

● Curb Box

Tax ID # 309.27-6-7

LSM-EC 10-21-49