

### LABOR AND MATERIALS

Copper	}	Connection		\$
Lead				
Curb	}	Cock	in.	\$
		Valve		
		T. S. & V.		
Service box	}	Short 3½ x 4½		\$
Old returned		Long 4½ x 5½		
		Buff or Rdway		
Ft. in.	}	Copper	Pipe at	\$
		G. I.		
		C. I.		
Nipples	in. at			\$
Bushings	to in. at			\$
Red'g	}	Coupl'gs	to in. at	\$
Inc'g				
Union	in. at			\$
Meter	in. at			\$
Lead Joints	at			\$
Compound Joints	at			\$
Maintenance Foreman				\$
Hrs. Water Maint. Man-1	at			\$
Hrs. Water Maint. Man-2	at			\$
Hrs. Garage Foreman	at			\$
Hrs. Labor	at			\$
Hrs. Compressor	at			\$
Compensation Ins. at \$		per C		\$
Trucking				\$
Pav't Patch				\$
				\$
				\$
				\$
O'head				\$

Blow off for Dead End

North Rd

St. No. \_\_\_\_\_  
Pl. No. \_\_\_\_\_  
Ave. No. \_\_\_\_\_

Name of Owner \_\_\_\_\_

Measured from # 11

---

Labor and Mat'l. Report Oct. 11 19 65

# 11

Main

Elev. of Main at tap \_\_\_\_\_

Gate at • 57' 2"      • Gate at 65' 10"

Curb Box Blow off stop

2-Curb boxes.

LSM-5C-3-10-61