

21
 Labor and Material Report Sat 24 195

no 2B on the Dome

House 21

Church

19' 4" - 4" ← 6' 8"

6' 8" ← 6' 8"

● Curb Box

6" Main Elev. of Main at tap 51.0

Gate at ● Gate at

● Curb Box

Tax ID # 302.20-16-5

John Smalley

21
 Labor and Material Report Sat 24 195

no 2B on the Dome

House 21

Church

19' 4" - 4" ← 6' 8"

6' 8" ← 6' 8"

● Curb Box

6" Main Elev. of Main at tap 51.0

Gate at ● Gate at

● Curb Box

Tax ID # 302.20-16-5

John Smalley

Labor and Materials

1	Lead Connection	\$	
1	Curb Cock	\$	
1	Service Box (Short 3' x 4' Old returned (Long 4' x 5' Buffalo	\$	
12	Ft. $\frac{3}{4}$ in. Cast <i>Copper</i> Pipe at	\$	
	Nipples	\$	
	Bushings	\$	
	Red'g Coup. ... to ... in. at	\$	
	Inc'g Coup. ... to ... in. at	\$	
	Union ... in. at	\$	
	Meter ... in. at	\$	
	Cu. Yds. Br. Stone at	\$	
	Cu. Yds. Sand at	\$	
	Bags Cement at	\$	
	Paving Brick { Mack Red Asphalt } at	\$	
1 1/2	Hrs. Foreman at	\$	
4 3/4	Hrs. Common Labor at	\$	
	Hrs. Mason at	\$	
1/2	Hrs. <i>Compressor</i> at	\$	
	Hrs. at	\$	
200	Builders' Use of Water	\$	
 at	\$	
	<i>Truck 100</i>	\$	
	<i>Payment</i>	\$	
 at	\$	
	Total	\$	<u>76.08</u>