

### Labor and Materials

Copper } Connection.....	9	\$ 3.20
Lead } .....		
Curb } Cock } .....	4 3	\$ 1.00
} Valve } .....		
} P. S. & V. } .....	1	
Service Box } Short 3/4x4 1/2 } .....		\$ 1.20
Old returned } Long 1 1/2x5 1/2 } .....		
} Buff. or Redway } .....		
9 Ft. .... in. } Copper } Pipe at.....	9	\$ 1.98
} Curb Iron } .....	1	
} Cast Iron } .....		
Nipples..... in. at.....		\$
Bushings..... to..... in. at.....		\$
Red'g } Couplings..... to..... in. at.....		\$
Inc'g } .....		
Union..... in. at.....		\$
Meter..... in. at.....		\$
Lbs. Br. Stone at.....		\$
Lbs. Sand at.....		\$
Bags Cement 'at.....		\$
Paving Brick } Mack } at.....		\$
} Red } .....		
} Asphalt } .....		
Lead Joints at.....		\$
Leadite Joints at.....		\$
5 Hrs. Foreman at.....	6 2/3	\$ 3.15
8 Hrs. Common Labor at.....	40 1/8	\$ 3.25
Hrs. Common Labor at.....		\$
Hrs. Mason at.....		\$
Hrs. Mason's Helper at.....		\$
2 Hrs. Compressor at.....		\$ 3.00
Compensation Ins.....		\$ 1.7
Trucking.....		\$ 1.00
Builders' Use of Water.....		\$

Total \$ 18.03

### Labor and Material Report

Aug. 10 19 29

9 Notes Dammed St.  
E.



● Curb Box

6" Main Elev of Main at tap 4 1/2

Gate at ● ● Gate at

● Curb Box

*Old tap disconnected*

Tax ID# 302.20-16-10