

Labor and Materials

1	Copper	Connection	3	\$ 2.60
	Lead		4	
1	Curb	Cock Valve	3 1/2 in.	\$ 2.30
		T.S. & V.	4	
1	Service Box	Short 3/4 x 4 1/2		\$ 1.40
	Old returned	Long 4 1/2 x 5 1/2		
		Buff. or Rdway		
23	Ft.	3/4 in. Copper	Pipe at	\$ 6.10
		Galv. Iron		
		Cast-Iron		
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g Inc'g	Couplings	to in. at	\$
	Union	in. at		\$
	Meter	in. at		\$
	Lbs. Br. Stone	at		\$
	Lbs. Sand	at		\$
	Bags Cement	at		\$
	Paving Brick	Mack Red Asphalt	at	\$
	Lead Joints	at		\$
	Leadite Joints	at		\$
2	Hrs. Foreman	at		\$ 1.25
18	Hrs. Common Labor	at		\$ 7.31
	Hrs. Common Labor	at		\$
	Hrs. Mason	at		\$
	Hrs. Mason's Helper	at		\$
2	Hrs. Compressor	at		\$ 3.00
	Compensation Ins.			\$.23
	Trucking			\$ 1.00
	Builders' Use of Water	Patch		\$ 25.00
Total \$				50.19

29-196 39A7BW

Labor and Material Report 11/14 1929

430 Main Drive

39A7BW
W

24' 11" ← 21' 5"

Curb Box

Main

Elev of Main at tap

Gate at ●

● Gate at

● Curb Box

Curb Top shed off

Tax ID# 302.20-3-21