

Labor and Materials

1/4 Copper	}	Connection.....	\$.....
Lead				
..... Curb	}	Cock Valve in.....	\$.....
		T. S. & V.		
..... Service Box		Short 3 1/2 x 4 1/2	}
Old returned	Long 4 1/2 x 5 1/2			
	Buff. or Rdway			
15 Ft. 3/4 in.	}	Copper	Pipe at.....	\$.....
		Galv Iron		
		Cast Iron		
..... Nipples		in. at.....		\$.....
..... Bushings		to..... in. at.....		\$.....
..... Red'g Inc'g	}	Conplings.....	to..... in. at.....	\$.....
..... Union		in. at.....		\$.....
..... Meter		in. at.....		\$.....
..... Lead Joints at.....				\$.....
..... Leadite Joints at.....				\$.....
..... Hrs. Foreman at.....				\$.....
..... Hrs. Chauffeur at.....				\$.....
..... Hrs. Tapper at.....				\$.....
..... Hrs. Labor at.....				\$.....
..... Hrs. Labor at.....				\$.....
..... Hrs. Compressor at.....				\$.....
..... Compensation Ins.				\$.....
..... Trucking.....				\$.....
..... Builders Use of Water.....				\$.....
.....				\$.....
.....				\$.....
.....				\$.....
.....				\$.....
.....				\$.....
.....				\$.....
.....				\$.....
.....				\$.....
.....				\$.....
.....				\$.....
.....				\$.....

St. 33W
 Pl. 50
 Ave. No. 50

Name of Owner
TAX ID # 302.19-25-25

Labor and Mat'l. Report 19

33W

23'8" 19'9"

● Curb Box

..... Main
Elev. of Main at tap.....

Gate at ●
● Gate at

● Curb Box