

LABOR AND MATERIALS

Copper	}	Connection		\$	
Lead					
Curb	{	Cock Valve T. S. & V. in.	\$	
Service Box Old returned			{	Short 3 $\frac{1}{2}$ "x4 $\frac{1}{2}$ "	
	Long 4 $\frac{1}{2}$ "x5 $\frac{1}{2}$ "	\$			
	Buffor Rdway				
Ft.	{	Copper Galv Iron Cast Iron	Pipe at	\$	
in.					
Nipples	in. at		\$		
Bushings	to .. in. at		\$		
Red'g Inc'g	}	Couplings	to .. in. at	\$	
Union			in. at	\$	
Meter	in. at		\$		
Lead Joints at			\$		
Leadite Joints at			\$		
Hrs. Foreman at			\$		
Hrs. Chauffeur at			\$		
Hrs. Tapper at			\$		
Hrs. Labor at			\$		
Hrs. Labor at			\$		
Hrs. Compressor at			\$		
Compensation Ins.			\$		
Trucking			\$		
Builders Use of Water			\$		
			\$		
			\$		
			\$		
			\$		
			\$		

St. 61W
 Pt.
 Ave. No. 65

Notre Dame

Name of Owner
Tax ID # 302.19-25-22

Labor and Mat'l. Report AUG 25 1939 19

61W

● Curb Box

..... Main Elev. of
Main at tap

Gate at ● ● Gate at

● Curb Box