

Labor and Materials

1	Copper	} Connection <sup>3/4"</sup>	.....	\$ 1.33	
1	Lead				
1	Curb	} Cock Valve T.S.&V. } <sup>3/4"</sup>	..... in	\$ 1.56	
1	Service Box				
1	Old returned	} Short 3 1/2 x 4 1/2 } Long 4 1/2 x 5 1/2 } Buff. or Rivet }	.....	\$ 1.38	
26	Ft. 3/4 in.				
		} Copper Galv. Iron } Cast Iron }	Pipe at	\$ 2.47	
	Nipples				
	Bushings	..... to	..... in. at	\$	
	Red'g Inc'g	} Couplings	..... to	..... in. at	\$
	Union				
	Meter	..... in. at	\$		
	Lbs. Br. Stone	at	\$		
	Lbs. Sand	at	\$		
	Bags Cement	at	\$		
	Paving Brick	} Mack Red Asphalt }	at	\$	
	Lead Joints				
	Leadite Joints	at	\$		
4	Hrs. Foreman	at	\$ 5 -		
5	Hrs. Common Labor	at <sup>Tapper</sup>	\$ 2.50		
4	Hrs. Common Labor	at	\$ 3.60		
	Hrs. Mason	at	\$		
	Hrs. Masons Helper	at	\$		
	Hrs. Compressor	at	\$		
	Compensation Ins	.....	\$ .34		
	Trucking	.....	\$ 1 -		
	Builders Use of Water	<sup>Patch</sup>	\$ 9 -		
Total				\$ 28.18	

*3/4 Renewell at 70 + 70 1/2. Note*



*16"* Main Elev. of Main at tap *4 ft*

Gate at ● Gate at

TAX ID # 302.19-28-12

● Curb Box

*Old tap shut off*

*Tap made by Dept.  
 Leak in old pipe no  
 application made*

*[Signature]*