

LABOR AND MATERIALS

Copper	}	Connection		\$	
Lead	}				
Curb	{	Cock Valve	} in.	\$	
	{	T. S. & V.	}		
Service Box	{	Short 3½x4½	}	\$	
Old returned	{	Long 4½x5½	}		
	{	Buff for Rdway	}		
Ft.	in.	{	Copper	} Pipe at	\$
		{	Galv Iron		
		{	Cast Iron		
Nipples	in.	at		\$	
Bushings	to	in.	at	\$	
Red'g	{	Couplings	} to	in.	\$
Inc'g	{		}		
Union	in.	at		\$	
Meter	in.	at		\$	
Lead Joints	at			\$	
Leadite Joints	at			\$	
Hrs. Foreman	at			\$	
Hrs. Chauffeur	at			\$	
Hrs. Tapper	at			\$	
Hrs. Labor	at			\$	
Hrs. Labor	at			\$	
Hrs. Compressor	at			\$	
Compensation Ins.				\$	
Trucking				\$	
Builders Use of Water				\$	
				\$	
				\$	
				\$	
				\$	
				\$	
				\$	

St. 75W
 Pl.
 Ave. No. 77

Notre Dame

Name of Owner

Tax ID # 302.19-25-17

Labor and Mat'l. Report **AUG 25 1939** 19

..... Main

Gate at ●

Elev. of
Main at tap.....

● Gate at

● Curb Box

Labor and Materials

1	Lead Connection	\$
1	Curb Cock	\$
1	Service Box { Short 3 1/2 x 4 Old returned { Long 4 1/2 x 5 Buffalo	\$
7	3/4 in. G. I. Pipe at	\$
	Nipples in. at	\$
	Bushings in. at	\$
	Red'g Coup to in. at	\$
	Inc'g Coup to in. at	\$
	Union in. at	\$
	Meter in. at	\$
	Cu. Yds. Br. Stone at	\$
	Cu. Yds. Sand at	\$
	Bags Cement at	\$
	Pav. Brick { Mack Red Asphalt } at	\$
2	Hrs. Foreman at	\$
2	Hrs. Com. Labor at	\$
	Hrs. Mason at	\$
	Hrs. at	\$
	Hrs. at	\$
	Builders' Use of Water	\$
	Trucks 100 at	\$
	at	\$
	at	\$
	at	\$
	at	\$
	Total	\$ 8.29

Labor and Material Report Aug 22 1923

1/2" tap at vacant lot next to 77 Notre Dame St



6" Main Elev. of Main at tap 47.50
Gate at ● Gate at ●

● Curb Box