

LABOR AND MATERIALS

Copper } Connection \$
 Lead }
 Curb { Cook Valve } in. \$
 T. S. & V. {
 Service Box } Short 3 1/2 x 4 1/2 } \$
 Old returned } Long 4 1/2 x 5 1/2 }
 } Buffer Rdway }
 8' 6" Ft. in. { Copper } Pipe at \$
 { Galv Iron }
 { Cast Iron }
 Nipples in. at \$
 Bushings to in. at \$
 Red'g } Couplings to in. at \$
 Inc'g }
 Union in. at \$
 Meter in. at \$
 Lead Joints at \$
 Leadite Joints at \$
 Hrs. Foreman at \$
 Hrs. Chauffeur at \$
 Hrs. Tapper at \$
 Hrs. Labor at \$
 Hrs. Labor at \$
 Hrs. Compressor at \$
 Compensation Ins. \$
 Trucking \$
 Builders Use of Water \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$

St. 77W
 Ph. Notre Dame
 Ave. No. 79

Name of Owner
Tax ID # 302.19-25-16

Labor and Mat'l. Report **AUG 25 1939** 19

77W
 40' 5"
 33' 6"
 22' 6"
 Curb Box

Main Elev. of Main at tap.....

Gate at ● ● Gate at

● Curb Box