

LABOR AND MATERIALS

1	Copper Lead	Connection	3/4"	\$
1	Curb	Cock Valve T.S. & V.	3/4" in.	\$
1	Service box Old returned	Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff or Rdway		\$
9	Ft.	3/4 in. Copper G.I. C.I. Pipe at		\$
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g Inc'g	Coupl'gs to in. at		\$
	Union	in. at		\$
	Meter	in. at		\$
	Lead Joints at			\$
	Compound Joints at			\$
	Maintenance Foreman			\$
	Hrs. Water Maint. Man-1 at			\$
	Hrs. Water Maint. Man-2 at			\$
	Hrs. Garage Foreman at			\$
	Hrs. Labor at			\$
	Hrs. Compressor at			\$
	Compensation Ins. at \$	per C		\$
	Trucking			\$
	Pav't Patch			\$
	Tap made Aug 5-57			\$
	by Gifford & Co.			\$
	O'head			\$

V
W-79

St. W-Notre Dame
Ave. No. 81

Name of Owner
Donald C. Wilcox

Labor and Mat'l. Report Aug 5 1957

● Curb Box

6" Main Elev. of Main at tap 5'

Gate at ● Gate at

Tax ID# 302.19-25-15

● Curb Box

Old Service disconnected at Main
Aug 5-57

LSM-SC-2-5 56