

LABOR AND MATERIALS

1	Copper	Connection	<u>3/4"</u>		\$	
	Lead	Cock				
1	Curb	Valve	<u>3/4"</u>	in.		
		T. S. & V.				
1	Service box	Short $3\frac{1}{2} \times 4\frac{1}{2}$				
	Old returned	Long $4\frac{1}{2} \times 5\frac{1}{2}$				
		Buff or Rdway				
11	Ft. <u>3/4"</u> in.	Copper		Pipe at		
		G. I.				
		C. I.				
	Nipples	in. at				
	Bushings	to in. at				
	Red'g					
	Inc'g	Coupl'gs to in. at				
	Union	in. at				
	Meter	in. at				
	Lead Joints	at				
	Compound Joints	at				
	Maintenance Foreman					
	Hrs. Water Maint. Man-1	at				
	Hrs. Water Maint. Man-2	at				
	Hrs. Garage Foreman	at				
	Hrs. Labor	at				
	Hrs. Compressor	at				
	Compensation Ins. at \$	per C				
	Trucking					
	Pav't Patch					
	<i>Tap by G. E. GORDON & Co.</i>					
	<i>2-5-3-60</i>					
	O'head					

St. _____
Pl. _____
Ave. No. 83

Name of Owner
Maynard Brooks

Labor and Mat'l. Report May 3 1960

● Curb Box

6" Main Elev. of Main at tap 4 1/2'

Gate at ● ● Gate at

● Curb Box

Tax ID # 302.19-24-6

LSM-5C-2.5 56